

B-BOX HIGH VOLTAGE INSTALLATION SHORT INSTRUCTION

V1.1

1.

BMU + Base

n=5-9 Module

2.

3.

4.

n	5	6	7	8	9
h	788	908	1028	1148	1268

5.

6.

7.

8.

Inverter

P+ P- COM

Internet







Ethernet cable

* 13.

9.






10a.

ON






10b.

ON






11.




n=5-9 Module

12.




13a. SMA Sunny Boy Storage 2.5



SMA Sunny Boy Storage 2.5 software version \geq SBS2.5-V2.04.23

13b. KOSTAL PIKO BA



KOSTAL PIKO BA software version \geq xxxxxxxxxxxxxxxx